



YHI POWER PTY LTD A B N 59 063 419 849

SYDNEY 8 Penelope Crescent, Arndell Park, NSW 2148
MELBOURNE 20-22 Venture Way, Braeside, VIC 3195
BRISBANE 1/141 Boundary Rd, Oxley, QLD 4075
PERTH 24 Ernest Clark Road, Canning Vale, WA 6155
ADELAIDE 8 Schenker Drive, Royal Park, SA 5014

Tel : 02 9672 4998 Fax : 02 9672 4920
Tel : 03 9588 1888 Fax : 02 9588 0838
Tel : 07 3379 1461 Fax : 07 3711 5066
Tel : 08 9456 2224 Fax : 08 9456 3331
Tel : 08 8240 3019 Fax : 08 8447 4026

WARRANTY STATEMENT

YHI POWER PTY LTD, ABN 59 063 419 849, warrants VISION Lithium-ion battery range, to the original purchaser, if purchased from YHI POWER branches in Australia - against defects in materials and workmanship, in the correct applications, under the manufacturer's prescribed conditions of use, maintenance and service, for the periods of time, from the date of goods delivery - as stated below in Warranty Conditions, and subject to the conditions contained herein. By this letter, we hereby declared that our **LFP Battery meet below standard:**

Lithium-ion Battery for UPS is under five years warranty and it should be used in indoor of temperature $25\pm 3^{\circ}\text{C}$ & humidity $\leq 85\%$ under proper installation & maintenance based on using manual.

For 5+5 warranty period details as below,

Warranty Period	FIXED COST
Up to 5 years	Free of cost=0
6th year	GOODS VALUE X 60%
7th year	GOODS VALUE X 70%
8th year	GOODS VALUE X 80%
9th year	GOODS VALUE X 90%
10th year	GOODS VALUE X 100%

Battery part:

Warranty invalid based on following situations.

1. Exceeding the warranty period.
2. Failure to follow up instructions such as: maintain, usage (use in wrong voltage), or unauthorized disassembly or repair caused damage.
3. The battery is not charged according to the charging requirements, resulting in different battery performance parameters, non-rechargeable and non-rechargeable.
4. Battery capacity decreases gradually with the increase of cycle time of charge/discharge, which is a normal phenomenon and acceptable.
5. Battery storage over 3 months without charging caused low capacity, this is irreversible loss and cannot repair or fixed.
6. Damage caused by the factor of irresistible (such as earthquake, fire, Lightning, etc.) or by human action deliberately.
7. The issues do not relate to product design, process, quality of manufacturing.

BMS

Battery management system

Warranty invalid based on following situations.

1. Exceeding the warranty period.
2. Without manufacturer's authorized installation, disassembly or maintenance.
3. Failure to follow up instructions such as: operation, wrong wiring or unauthorized disassembly or repair caused damage.
4. Use the non -matched power adapter powering product caused damage.
5. Exceeding system usage conditions (included high/ low voltage, high current, high temperature, low humidity,) caused damage or failure.
6. Damage caused by natural disaster such as earthquake, fire, lightning etc. or by human action deliberately.
7. The issues do not relate to product design, process, quality of manufacturing.